

Mitsubishi hoist

Sales & Service


N o . 855-0229

Notice of Parts codes changes

Thank you for selecting a Mitsubishi hoist and related products. This letter is to notify the parts codes changes.

1. Object parts

		Part code		Changes
Part name	Voltage	Before change	After change	
Brake coil	200V Class	03G218	03G232	• Administration number changes 200V Class : P382648G01→PF57552G01 400V Class : P382649G01→PF58144G01
	400V Class	03G231	03G233	
Magnet assembly	200V Class	03H121	03H123	The coil figure number changes(Above) The elimination of the clamps The addition of the oilless metal assembly (03H14V)
	400V Class	03H122	03H124	



2. Schedule for the changes

- ① Brake coil・・・production from Sep, 2010.
- ② Magnet assembly・・・production from Nov, 2010.

3. Reason of changes

- (1) The partial change of the coil wire material.
- (2) The improvement on customer satisfaction.
 - ① Since there are many requests for the addition of the oilless metal.
 - ② Since it is not necessary to replace the clamps in general.

4. Others

- (1) The replacement guide of the oilless metal・・・Please replace the oilless metal if the oilless metal is worn out when the magnet assembly is replaced. Be careful when the oilless metal is pressed into magnet casing.
- (2) The purchase of the clamps・・・Please order the clamps separately when they are necessary.
- (3) The parts codes of Magnet assembly, Brake assembly and Brake・motor assembly are not changed.

Subject	Notice of the parts codes changes	Date of issue	August 30, 2010	Notified to
		MITSUBISHI ELECTRIC FA INDUSTRIAL PRODUCTS CORPORATION 1-1-1 Imajuku-Higashi, Nishi-ku, Fukuoka 819-0192 TEL 092-805-3400		Sales agent