

Mitsubishi hoist

Sales & Service

No. 855-0228

Notice of Grease Change of Traversing Deceleration Part

Thank you for selecting a Mitsubishi hoist and related products. This letter is to notify the grease change of the traversing deceleration part.

1. Subject Models and Changes

Subject Models . . . 1/2t~5t Monorail type, Low-head type (S series, R series, U series, UR series)

Changes (1)The lubricant(grease) for the traversing deceleration part is changed.

	Before change	After change
Lubricant	Alvania EP-2 (Fill approx. 1/3 of the space)	Moly PS grease No.2 (Application all around)

(2) The ball bearings are changed to sealed type ball bearings. (ZZ)

2. Schedule for Changes

The changes are carried out for the orders assembled on July, 2010 or after.

3. Reason of Changes


The improvement for the lubricating ability and the quality.

4. Precaution Statement

(1)The revision of Instruction Manual and Service hand book are carried out next revision.

(2)Please prepare Moly PS grease No.2 for maintenance service.

(Moly PS grease has already been used for the joint of motor axis.)



Subject	Notice of the grease change of the traversing deceleration part.	Date of issue	July 23, 2010	Notified to
		MITSUBISHI ELECTRIC FA INDUSTRIAL PRODUCTS CORPORATION 1-1-1 Imajuku-Higashi, Nishi-ku, Fukuoka 819-0192 TEL 092-805-3400		Sales agent