

Mitsubishi hoist

Sales & Service

N o . 855-0231

Notice of Brake Disk Change for Hoist

Thank you for selecting a Mitsubishi hoist and related products. This letter is to notify the brake disk change for Hoist.

1. Subject Parts codes and Models :

Before change		After change		Subject Model	
Part code	Brake disk Drawing No.	Part code	Brake disk Drawing No.	Existing Model	Old Model
03G103	P791490G02	03G125	PF58459G01	S-1/2, R-1, etc	S-1-Early Models, R-2-Early Models, etc
03G107	P791490G01	03G126	PF58460G01	S-1-Explosion- Proof Type	S-2-Early Models, R-2.8-Early Models, etc

2. Schedule for Change

- Hoist Products : The changes are carried out for the orders assembled on May, 2011 or after.
- Parts After Sales : After running out the present stock.(sometime around May, 2011)

3. Reason of Changes


- The change of brake disk manufacturer.

4. The compatibility of the New and old brake disk

- There is no dimensional compatibility problem in installing the brake disk, although the parts codes are changed.

5. The differences between the new and old brake disks.

- Indication...The model number of Brake lining material is stamped by immortal ink.
- Color...Old(light brown), New(green-brown)



Subject	Notice of the brake disk change for Hoist.	Date of issue	May 1, 2011	Notified to
		MITSUBISHI ELECTRIC FA INDUSTRIAL PRODUCTS CORPORATION 1-1-1 Imajuku-Higashi, Nishi-ku, Fukuoka 819-0192 TEL 092-805-3400		Sales agent