

# Mitsubishi hoist

## Sales & Service

N o . 855-0247

### Notice of AC brake coil changes


Thank you for selecting a Mitsubishi hoist and related products.  
This letter is to notify the AC brake coil changes.

#### 1. Subject Parts : AC brake coils

		Subject Models
Part Name	Part Code	
AC brake coil	03G232 (200V)	S-5-O, ② HY-5A HY-7.5A-O, ③~⑥ HY-10A-O, ③~⑥ HY-15A-O, ③~⑥ HY-20A-O, ③~⑥ HY-20A-O, ③~⑥ HY-30A-O, ③~⑥ S-7.5 S-10 S-15 S-20 S-30 S-5-VT, VT2 S-10~30-VT HY-10A~30A-VT⑥
	03G233 (400V)	

#### 2. Changed Contents

The right figure The cushion rubbers ③ ④ ③ ⑥ are added.  
(There is no change on the part code)



#### 3. Schedule for Changes :

The changes sre carried out on Oct, 2012.(After running out the present stock)

#### 4. Reason for Changes :

The AC brake coils are changed for the improvement on the quality.

Subject	Notice of AC brake coil changes	Date of issue	Oct 1, 2012	Notified to
		MITSUBISHI ELECTRIC FA INDUSTRIAL PRODUCTS CORPORATION 1-1-1 Imajuku-Higashi, Nishi-ku, Fukuoka 819-0192 TEL 092-805-3400		Sales agent