

Mitsubishi hoist

Sales & Service


No. 855-0251

Notice of a part for a 7.5ton hook block change

Thank you for selecting a Mitsubishi hoist and related products.
This letter is to notify a part for a 7.5ton hook block change.

1. Changed Contents

The shape of a cover which is in the thrust-bearing part is changed.



2. Subject of Types

HY-A, S, U2 type hoists(7.5ton)

3. Compatibility

This change has compatibility with former cover.
(The shape is only changed)

※The Part Code for service parts is not changed

Part Code	Part Number
03H435	2581211

4. Schedule for Changes

- Products ... From Oct, 2013(After running out the present stock)
- Service Parts ... From Oct, 2013

5. Reason for Changes

For a productivity increase

subject	Notice of a part for a 7.5ton hook block changes	Date of issue	July 19, 2013	Notified to
		MITSUBISHI ELECTRIC FA INDUSTRIAL PRODUCTS		Sales agent
		CORPORATION		
		1-1-1 Imajuku-Higashi, Nishi-ku, Fukuoka 819-0192		
		TEL 092-805-3400		