# Mitsubishi hoist

## Sales & Service

No. 855-0310

## Notice of the change in hoist brake disk

We highly appreciate for your continuous sales support on Mitsubishi hoist and related items. This time, we would like to make an announcement for change in hoist brake disk accordingly.

### 1. Changed contents


Changes will be made on part of the brake disk that have been purchased from two companies as shown below. (Based on sales & service No. 855-0290 issued in July 2017)

## 2. Subject models and used brake disk


<Current>

Representative Applicable Model	Brake disk	
	Hoist Product	Maintenance Parts
S-5-3 Model, HY, S-10~30 Etc.	A company	B company
S-1-Early Production Model, R-2-Early Production Model, S-1/2, R-1 Etc.	A company	B company
S-2-Early Production Model, R-2.8-Early Production Model,	A company	B company
S-1-Explosion Proof Model Etc.	A Company	b company

### <After change>







Indication: TOMBO RH6-F (Written in red letter)

## 3. Schedule for change

Changes will be made around May 2019.

(After inventory of A company type of brake disk is consumed, B company brake disk will be switched sequentially)

#### 4. Others

No changes will be applied for maintenance parts as mentioned above.

ubject	hoist brake disk	Date of issue	March 20, 2019
		MITSUBISHI ELECTRIC FA INDUSTRIAL PRODUCTS CORPORATION	
S		1-1-1 Imajuku-Higashi, Nishi-ku, Fukuoka 819-0192	
		TEL 092-805-3400	