

# Mitsubishi hoist

## Sales & Service

N o . 855-0237

### Notice of parts code changes for DC brake

Thank you for selecting a Mitsubishi hoist and related products. This letter is to notify the parts code changes for DC brake.

1. Subject Parts : Brake coils(Hoisting) for U, S – 2.8 (3)

		Part Code		Changes
Part Name	Voltage	Before change	After change	
Brake coil	200V class	03G217	03G243	• Administration No. 200V class : P647637G02→PF53513G02 400V class : P647855G01→PF54363G02
	400V class	03G250	03G253	

2. Schedule for Changes :

The changes are carried out on Jan, 2012.(After running out the present stock)

The existing parts codes are extinguished.

3. Reason for Changes :

( 1 ) Parts commoditizing (U, S – 5 (3))

4. Others :

( 1 ) There is no problem with the combination use of the new brake coils and the existing brake coils.(03G217, 03G250)

Subject	Notice of parts code changes for DC brake	Date of issue	Dec 28, 2011	Notified to
		MITSUBISHI ELECTRIC FA INDUSTRIAL PRODUCTS CORPORATION 1-1-1 Imajuku-Higashi, Nishi-ku, Fukuoka 819-0192 TEL 092-805-3400		Sales agent